

QUICK INSTALLATION GUIDE



CONTACT

KFA AG
 WEISSHOFSTR. 40
 P.O. BOX 1024
 4000 LÜTTICH 1
 BELGIUM

PHONE +32 (0)3217 40 11 00
E-MAIL info@kfa.be
WEB www.kfa.be

KFA2

6-axis TDR sensor with single rod, wire rope or coiled probe for continuous level measurement and gain level detection in liquids and light solids, with wiring and mounting probe.

DOCUMENT DESCRIPTION

This quick installation guide gives instructions for mounting, wiring and basic configuration of KFA2. This will be sufficient to achieve a fully functional sensor in most applications. For further details and advanced configuration of KFA2, please contact your local distributor or KFA directly.

INSTALLATION PROCEDURE

